



NOTES

1. DETACH EXISTING CONDUIT ON OUTSIDE OF CAB COLUMNS AND REATTACH AFTER COMPLETION OF COLUMN STRENGTHENING. DO NOT CUT WIRING OR DISRUPT SERVICE OF CONDUIT CIRCUITS.

SCALES SHOWN FOR 22" X 34" SHEET. ADJUST SCALES FOR OTHER SIZES.		PAGE OF 63	
DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION		ATHENS (ATHENS MUNICIPAL AIRPORT) GA	
ATHENS		GA	
REVIEWED BY	SUBMITTED BY	APPROVED BY	
	VIRGIL HOOPER, PE.	MARK BEEKMAN	
DESIGNED	SNG	ISSUED BY	DATE
DRAWN	SNG	ATLANTA TERMINAL ENGINEERING CENTER	03/31/2010
CHECKED	RAB	DRAWING NO.	804669
7000 CENTRAL PARKWAY, SUITE 1475 ATLANTA, GEORGIA 30328 HEI JOB NUMBER: 09033.00		AHN-D-ATCT-S301	